2.2 Hardware Ports



Hardware Ports

	Port	Function
1	RJ45 Port	Ethernet connection
2	DC 5V Power Jack	Power input
3	HDMI Port	Display output
4	Audio-Out Jack (3.5mm)	Stereo audio output
5	RS-232 Jack (3.5mm)	RS-232 control port
6	Reset Button	Device reset
7	microSD Card Slot	microSD card for additional storage
8	USB-A Port	USB mouse/keyboard and USB thumb drive
9	USB-C port	USB mouse/keyboard and USB thumb drive

Steps to connect NovoDS DS301 to your display.

Step 1 : Connect the NovoDS 301 to a display via the HDMI output port

Step 2 : Connect the AC-DC power adaptor to the DC 5V power jack

Spep 3 (optional) : Connect an Ethernet cable to the RJ45 port (if you need to use LAN connection)

The device comes with a mounting bracket. Typically you can use it to attach the NovoDS device to the back of the display or on the wall.