# 2.1 Hardware Installation

Installing X500 is very simple and straight-forward. The following two figures summarize the key peripheral ports available. (You may refer to the Quick Start Guide for details.)

1	Port USB-A
2	Micro SD Card Slot
3	RJ45 (Ethernet)
4	HDMI OUT
5	Port Type-C
6	AUDIO OUT
7	RESET
8	DC Jack

X500 Key Peripheral Ports
Typically,
users just need to attach the following four ports

1. Attach the WiFi antenna
2. Connect the HDMI cable
3. Plug in the Ethernet port
4. Apply the DC power with the AC-DC adaptor provided

The AC-DC power adaptor comes with several types of plugs, one of which should be suitable to the power outlets used in your country or region.

AC-DC Adaptor with Changeable Plug