NC-X910/NC-X710 Release Notes

V5.0.2

2026/04/24

New Features

- Added support for the new version of LauncherPlus WQL-500: Integrated the updated LauncherPlus connection guide illustration onto the home screen UI.
- Added support for Miracast: Enabled native Windows/Android wireless projection.
- NovoDS Auto-Play: Implemented an auto-play feature for digital signage content upon device startup.

Enhancements & Changes

- BYOM License Removal: Discontinued the requirement for a license key; BYOM features are now available out-of-the-box.
- NC-X710 LauncherPlus Auto-Pairing: Enhanced the auto-pairing mechanism to support environments where Wi-Fi or Hotspot security passwords are enabled.
- NC-X910 LauncherPlus Restriction: Discontinued support for LauncherPlus on the US model; all LauncherPlus-related information has been removed from the home screen UI.

Bug Fixes

- Airplay Latency: Resolved a lag and latency issue when streaming via AirPlay.
- 5GHz LauncherPlus Connectivity: Fixed a bug where LauncherPlus could successfully pair over 5GHz Wi-Fi but failed to establish a projection connection.
- Full-Screen Mouse Trapping: Fixed an issue where the

mouse cursor could not reach the far-right edge of the screen when projecting in full-screen via Desktop Streamer App at 1080p resolution.
- Local Upgrade Failure: Resolved a firmware corruption issue that caused the “Local Upgrade” process to fail.
- On-Screen Annotation Displacement: Fixed a coordinate mapping bug on NC-X910 and NC-X710 when an external mouse was connected. The on-screen annotation position will no longer drift or misalign when switching the display resolution from 4K to 1080p during a DSA projection session.
- AirNote Clearing Issue: Fixed a bug in AirNote where erasing annotations became unresponsive if the AirNote screen was refreshed prior to clicking the delete/clear button.
- NovoDS YouTube Playback: Resolved a playback failure issue with YouTube video widgets within NovoDS.
- NovoDS Schedule Playback: Fixed a scheduling conflict that caused playlist timetables to execute incorrectly.
- NovoDS Portrait Layout Disruption: Fixed a rendering layout bug where portrait playlists displayed abnormally.
- NovoDS Portrait Mode Orientation: Resolved an issue preventing content from playing back when the device was set to Portrait Mode orientation.

V5.0.1

2024/8/5

Notes

- To fully exercise the new features developed in this release, the following Software are required
    - Remote Manager with version V3.3.5 or above.
    - iOS NovoConnect App with version V4.5.5 or above.
    - Android NovoConnect App with version V4.5.6 or

above.
- NovoConnect Software with version V4.5.8 or above.

New Features

- Support for NovoConnect NC-X900 and NC-X700 full function.
- Support for Remote Manager Cloud.
- Support for SysControl – Network-based device control, default is Disabled.
- Support for HDMI-CEC, default is Disabled.
- HDMI-IN supports 4K@30.
- New homepage background design, changes daily with a total of 15 backgrounds.
- Added landing page QR code to the homepage.

Enhancements & Changes

- Updated BYOM driver to V1.46.
- Move SysControl – Network-based device control interface to NT Settings.
- Optimize NT Livenote:
  - NT Livenote will not be displayed when the device is not connected to a mouse; it will appear once a mouse is connected.
  - Ability to move the central icon in NT Livenote.
  - The central icon in NT Livenote will display the currently selected function.