NovoTouch TK-2 Release Notes

V1.0.3

2024/10/4

Enhancement & Changes

- Remove the icon on the right side of each app in the Recent list; keep the left swipe to clear the app.
- Remove the 4096×2160 resolution setting from the EDID.

Bug fixes

- Fixed an issue with TK2 (NT-B1001) where upgrading to the new version sets the HDMI CEC default to Disabled, but it is actually Enabled.
- Fixed an issue where manually switching between "Soft" and "Bright" in picture mode fails.
- Fixed an issue in Whiteboard where using the eraser to clear part of the strokes results in all strokes being cleared.
- Fixed incorrect default values for the eraser and brush in Whiteboard.
- Fixed RS-232: Picture mode: Setting Soft/Bright causes TK2 (NT-B1001) to display the opposite.
- Fixed RS-232: Contrast: Get Contrast reading is incorrect.
- Fixed an issue with TK2 (NT-B1001) where connecting a USB and performing a factory reset clears the USB after completion.

V1.0.2

2024/8/1

New Features

- Support NT Announcement.
- Support SysControl — Network-based device control, default is Disabled.
- Users can configure Startup Channel (video source) and show/hide of Sidebar and Launch-Pad:
  - Startup channel can be set to one of Android, HDMI1, HDMI2, HDMI3, OPS, FRONT_HDMI, and Type-C. Default channel is Android.
- In NT Settings, add HDMI Out configuration to the Display page.
- Whiteboard supports PDF files.

Enhancement & Changes

- HDMI-CEC default changed to Disabled.
- Change the NT Launcher homepage Help & Support URL.
- Power key modified to one press for Standby, long press for 3 seconds to display the menu with Power Off and Reboot options.

Bug fixes

- Fixed TK2 (NT-B1001) when playing 4K videos on YouTube. Switching to 2160p causes a green screen, and 1440p shows flickering lines.
- Fixed TK2 (NT-B1001) HDMI connection with laptops experiencing random screen flickering or no signal.
- Fixed an issue where Static IP settings were switched to DHCP after reboot.
- Fixed OPS PC unable to switch to Type-C using RS-232.
- Fixed abnormal RS-232 commands for some settings.
- Fixed system lag issue when opening multiple apps.
- Fixed TK2 (NT-B1001) when using HDMI with laptops; continuous use of NT Snapshot results in a black screen.
- Fixed NovoConnect Software connection for full-screen projection; sound playback causes video stuttering.
- Fixed issue where the page list displays blank after adding multiple pages in Whiteboard.

V1.0.1

2024/4/19

Notes

- Model name: TK652i, TK752i, TK862i
- To fully exercise the new features developed in this release, the following Software are required
    - Remote Manager with version V3.3.5 or above.
    - NovoConnect Software and Wi-Fi Launcher with version V4.5.8 or above.
    - Android NovoConnect App with version V4.5.6 or above.
    - iOS NovoConnect App with version V4.5.5 or above.

New Features

- NovoConnect APP (screen mirroring) is upgraded to the Full version.
    - New feature, "Screen broadcast", is added.
- Launch-Pad is added at the bottom of the screen to provide quick access to frequently-used Apps. (Users are able
  to customize the Apps in Launch-Pad.)
- Introduced a suite of floating Apps, enabling users to bring up multiple Apps on the screen, including NT Timer,
  NT Calculator, NT Spotlight, NT LiveNote, NT Camera, NT Browser, NT Player.
- "Screen Lock" feature is added.
- Users can customize wallpaper of the Home-screen.
- Remote Manager Cloud is supported.
- Snapshot tool is added to the Sidebar.
- New features are added in NT Settings
    - SysControl – Network-based device control. Its default state is Disabled
    - Auto Reboot

- Power & Sleep
- New features are added in AV Settings
    - HDMI-CEC (default Enabled)
    - Low Blue Light (On/Off)

Enhancements & Changes

- Optimized POWER key behavior
    - Single click to enter Standby mode
    - "Press and hold" to prompt Power-Off/Reboot dialog
- The NT APP Store has been updated as follows:
    - New category, "Recommended Installation", is added, including Google Drive, VLC, Zoom Cloud Meetings, WPS office, NovoDS mobile.
    - MX Player is added to "Video Player & Editors"
    - Google Gallery is added to "Google"
- Enabled LauncherPlus Pairing
- Touchback is enabled for LauncherPlus Lite software.
- Timezone is automatically adjusted to match the region setting.

Bug Fixes

- Various bug fixes to improve system stability.