

3.1.1 Start Screen Projection:

1. Plug a **LauncherPlus** into the PC's or device's USB-C port.
2. The **LauncherPlus** will connect automatically to the paired **Novo** devices.

Once the connection is established, your device's screen will be displayed automatically on the projected screen, and the LED indicator will turn light blue.

